



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead Paint Chip Analysis Report

Client: Environmental Health Consultants Inc.
2304 Jefferson Park Avenue
Charlottesville, VA 22903

Report Number: 10-05-02091

Received Date: 05/17/2010
Analyzed Date: 05/18/2010
Reported Date: 05/18/2010

Project/Test Address: 319 Rutherford St

Client Number:

48-1735

Laboratory Results

Fax Number:

Lab Sample Number	Client Sample Number	Collection Location	Pb (ug/g) ppm	% Pb by Wt.	Narrative ID
10-05-02091-001	R5-14-10-1P	BLDG A W BRICK WALL	8000	0.80	
10-05-02091-002	R5-14-10-2P	BLDG A W BRICK WALL	4400	0.44	
10-05-02091-003	R5-14-10-3P	BLDG A E BRICK WALL	1100	0.11	
10-05-02091-004	R5-14-10-4P	BLDG A E BRICK WALL	850	0.085	
10-05-02091-005	R5-14-10-5P	BLDG C E BRICK WALL	760	0.076	
10-05-02091-006	R5-14-10-6P	BLDG C S BRICK WALL	2400	0.24	
10-05-02091-007	R5-14-10-7P	BLDG C SECTION 2 N BRICK WALL	410	0.041	
10-05-02091-008	R5-14-10-8P	BLDG C SECTION 2 E BRICK WALL	650	0.065	
10-05-02091-009	R5-14-10-9P	BLDG C AUTO SHOP E BRICK WALL	550	0.055	
10-05-02091-010	R5-14-10-10P	BLDG D W BRICK WALL	2500	0.25	
10-05-02091-011	R5-14-10-11P	BLDG D N BRICK WALL	610	0.061	

Environmental Hazards Services, L.L.C

Client Number: 48-1735

Report Number: 10-05-02091

Project/Test Address: 319 Rutherford St

Lab Sample Number	Client Sample Number	Collection Location	Pb (ug/g) ppm	% Pb by Wt.	Narrative ID
10-05-02091-012	R5-14-10-12P	BLDG E W BRICK WALL	880	0.088	
10-05-02091-013	R5-14-10-13P	BLDG E N BRICK WALL	4400	0.44	
10-05-02091-014	R5-14-10-14P	BLDG E 2ND LVL BRICK WALL	620	0.062	

Method: EPA SW846 7420

Reviewed By Authorized Signatory:



Deborah Britt
QA/QC Clerk

The HUD lead guidelines for lead paint chipers are 0.50% by Weight, 5000 ppm, or 1.0 mg/cm². The Reporting Limit (RL) is 10.0 ug Total Pb. Paint chip area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. EHS sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714.

LEGEND	Pb= lead	ug = microgram	ppm = parts per million
	ug/g = micrograms per gram	Wt. = weight	

10-05-02091



Due Date:
05/18/2010
(Tuesday)



Environmental Health Consultants, Inc.
2304 Jefferson Park Avenue
Charlottesville, VA 22903
Phone & Fax: (434) 977-1409

Laboratory Sample Analysis Request

Time Requested: Lead-in - Paint (24 hrs)

Project Description: 319 Rutherford St

Instructions: Please fax results as soon as analyses completed. Repeat all sample information shown below on final lab report. Please sign and return this form with written report. Other special requests: email tjloving@comcast.net

Sample #	Special Notes	Person/Area Sampled	Activity Occurring	Pump #	Pump Flow Rate (LPM)	Start Time	Stop Time
R5-14-10-1P		Bldg A - Gray paint on west side brick wall					
-2P		Bldg A - White & green paint on west side brick wall					
-3P		Bldg A - Gray paint on east side brick wall					
-4P		Bldg A - White paint on east side brick wall					
-5P		Bldg C - White paint on east side brick wall					
-6P		Bldg C - Gray paint on south side brick wall					
-7P		Bldg C - Section 2 - Gray paint on north side brick wall					
-8P		Bldg C - Section 2 - White paint on east side brick wall					
-9P		Bldg C - Auto Shop - White paint on east side brick wall					
-10P		Bldg D - Gray paint on west side brick wall					

Samples submitted by: [Signature]

Date: 5-14-10

Samples received by: [Signature]

Date: 5/17/10

cm
5/17/10



10-05-02091

Environmental Health Consultants, Inc.
2304 Jefferson Park Avenue
Charlottesville, VA 22903
Phone & Fax: (434) 977-1409

Laboratory Sample Analysis Request

Analysis and Turnaround Time Requested: Lead-in - Paint

Project Description: 319 Rutherford St (cont)

Instructions: Please fax results as soon as analyses completed. Repeat all sample information shown below on final lab report. Please sign and return this form with written report. Other special requests: _____

Sample #	Special Notes	Person/Area Sampled	Activity Occurring	Pump #	Pump Flow Rate (LPM)	Start Time	Stop Time
-11P		Bldg D - Gray paint on north side brick wall					
-12P		Bldg E - Gray paint on west side brick wall					
-13P		Bldg E - White paint on north side brick wall					
-14P		Bldg E - White paint on north side 2nd Level brick wall					

Samples submitted by: [Signature]

Date: 5/14/10

Samples received by: [Signature]

Date: 5/17/10